



MASSEY FERGUSON 35 WIRING DIAGRAM DIESEL 3 CYLINDER WITH DYNAMO (GENERATOR)




MASSEY FERGUSON 35 WIRING DIAGRAM DIESEL 3 CYLINDER WITH ALTERNATOR



674 96AH battery



Starter & battery lead note :
One of the reasons for starter motor failure is battery leads which are too light. Use 50mm braided cable. Fix earth cable lug to 7/16" bolt on bell housing.

Insulate wires with a good quality insulation tape and place in protective flexible auto wire sleeve



- 4mm wire
- 4mm wire
- 2.5mm wire
- 2.5mm wire
- 2.5mm wire

MASSEY FERGUSON 35 WIRING DIAGRAM LIGHTS & HOOPER CIRCUITS



MASSEY FERGUSON 135 INDICATORS

